#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-002072 Address: 333 Burma Road **Date Inspected:** 01-Apr-2008

City: Oakland, CA 94607

OSM Arrival Time: 600 **Project Name:** SAS Superstructure **OSM Departure Time:** 1730 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

**CWI Name: CWI Present:** Yes N/A No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

**Bridge No:** 34-0006 **Component:** OBG

### **Summary of Items Observed:**

UT-DP042-002

This Quality Assurance (QA) inspector arrived at ZPMC for observation of the SAS super structure fabrication and performed Ultrasonic Examination (UT) on the closed rib Partial Joint Penetration (PJP) weld joints. This Verification was performed after ZPMC performed there UT testing. It was noted that on weld DP042-002 there were multiple locations that had less than 9.6mm of Depth Of Penetration (DOP). The Deck Panel noted above is still process due to the QA verification performed noted multiple areas that had to be evaluated for one 800mm section which reduced the time frame aloud to perform the QA verification. Of this area after evaluation it was determined that the indications were acceptable due to the thickness material of the closed rib being a minimum of 12.7mm and a maximum of 13.5mm. This QA inspector will complete the UT verification tomorrow during his shift.

#### **Summary of Conversations:**

No conversations noted today.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Pat Lowry, (858) 344-2712, who represents the Office of Structural Materials for your project.

**Inspected By:** Riley, Ken Quality Assurance Inspector

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

**Reviewed By:** Hager,Craig QA Reviewer